

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
PA,
51-GERM,
64-

Cliveden (Chew Mansion)
6401 Germantown Avenue
Philadelphia
Philadelphia County
Pennsylvania

HABS No. PA-1184

Documentation: 17 sheets (1972, including site plan, plans, elevations,
sections, details, landscape plan, plans and elevations
of barn)
37 exterior photos (1967, 1972)
50 interior photos (1967, 1972)
9 data pages (1972, 1983)

Photographs by Jack E. Boucher, 1972, unless otherwise noted.

EXTERIOR VIEWS

- PA-1184-1 GENERAL VIEW, FROM SOUTH. Photographed by Cortlandt V.D. Hubbard, 1967
- PA-1184-2 GENERAL VIEW, FROM SOUTHWEST. Photographed by Cortlandt V.D. Hubbard, 1967
- PA-1184-3 GENERAL VIEW, FROM SOUTH, CLOSER
- PA-1184-4 GENERAL VIEW, FROM SOUTHWEST, CLOSER
- PA-1184-5 SOUTH (FRONT) ELEVATION
- PA-1184-6 EAST ELEVATION, FROM SOUTHEAST
- PA-1184-7 WEST ELEVATION, FROM WEST
- PA-1184-8 WEST ELEVATION AND CURVING ONE-STORY ARCADE (LEFT), FROM WEST
- PA-1184-9 GENERAL VIEW OF REAR ELEVATIONS OF HOUSE, ADDITION AND WINGS, FROM NORTH
- PA-1184-10 EAST WING, FROM SOUTH
- PA-1184-11 WEST WING, FROM SOUTHWEST
- PA-1184-12 NORTH (REAR) ELEVATION OF WEST WING, FROM NORTH
- PA-1184-13 REAR OF WEST WING, FROM NORTHWEST. ARCHED OPENING HOUSES
WATER PUMP
- PA-1184-14 REAR OF WEST WING, FROM NORTHEAST

(continued on page 2)

DETAIL VIEWS:

- PA-1184-15 FRONT ELEVATION
- PA-1184-16 FRONT ENTRANCE. Photographed by Cortlandt V.D. Hubbard, 1967
- PA-1184-17 FRONT ENTRANCE
- PA-1184-18 FRONT PAVILION
- PA-1184-19 FRONT PAVILION PEDIMENT
- PA-1184-20 URNS, DORMERS AND CHIMNEYS ON FRONT ROOF
- PA-1184-21 ROOF DETAIL
- PA-1184-22 URNS, DORMER AND CHIMNEY
- PA-1184-23 TYPICAL URN
- PA-1184-24 CORNICE, DORMER AND URNS
- PA-1184-25 VIEW OF REAR CORNER, LOCATED AT THE JUNCTURE OF MAIN BLOCK
AND 19th CENTURY ADDITION, FROM NORTH
- PA-1184-26 REAR CORNER, FROM EAST
- PA-1184-27 TYPICAL FENESTRATION, EAST ELEVATION
- PA-1184-28 SHUTTER DOG AND SHUTTER HINGE
- PA-1184-29 WATER PUMP, LOCATED AT REAR OF WEST WING
- PA-1184-30 WATER WELL AND PUMP OUTLET, PART OF WATER PUMP HOUSING IN
WEST WING
- PA-1184-31 STONework OF FRONT ELEVATION
- PA-1184-32 STONework OF WEST WING

INTERIOR VIEWS

FIRST FLOOR:

- PA-1184-33 GENERAL VIEW OF MAIN HALL, FROM SOUTHEAST. Photographed by
Cortlandt V.D. Hubbard, 1967
- PA-1184-34 MAIN HALL, LOOKING TOWARDS REAR PORTION OF HALL, FROM SOUTH
- PA-1184-35 MAIN HALL, LOOKING TOWARDS MAIN DOORS, FROM NORTH

(continued on page 3)

- PA-1184-36 MAIN HALL, WITH MAIN DOORS OPENED, LOOKING SOUTHWEST. Photographed by Cortlandt V.D. Hubbard, 1967
- PA-1184-37 MAIN HALL, WITH MAIN DOORS CLOSED, LOOKING SOUTHWEST. Photographed by Cortlandt V.D. Hubbard, 1967
- PA-1184-38 MAIN HALL, LOOKING TOWARDS SOUTHEAST ROOM
- PA-1184-39 MAIN HALL, LOOKING TOWARDS SOUTHWEST ROOM
- PA-1184-40 REAR PORTION OF MAIN HALL, FROM SOUTH
- PA-1184-41 MAIN DOORS WITH LOCK RAIL, MAIN HALL
- PA-1184-42 SOUTHEAST ROOM. Photographed by Cortlandt V.D. Hubbard, 1967
- PA-1184-43 SOUTHEAST ROOM. NOTE FINE SECRETARY
- PA-1184-44 PARLOR, LOCATED IN THE NORTHEAST PART OF THE MAIN BLOCK, LOOKING SOUTH. Photographed by Cortlandt V.D. Hubbard, 1967
- PA-1184-45 PARLOR
- PA-1184-46 PARLOR
- PA-1184-47 SOUTHWEST ROOM
- PA-1184-48 DINING ROOM, LOCATED IN THE NORTHWEST PART OF THE MAIN BLOCK, LOOKING SOUTHEAST. Photographed by Cortlandt V.D. Hubbard, 1967
- PA-1184-49 DINING ROOM, LOOKING NORTHEAST
- PA-1184-50 DINING ROOM. NOTE FIREPLACE AND PANELED WOODWORK
- PA-1184-51 PANTRY HALL
- PA-1184-52 CELLAR, CENTRALLY LOCATED
- PA-1184-53 ONE OF CELLAR ROOMS
- PA-1184-54 FRONT ROOM, EAST WING, LOOKING NORTHEAST
- STAIRWAY SECTION:
- PA-1184-55 STAIRLANDING WITH FALSE DOOR TO REAR ADDITION, LOOKING NORTH
- PA-1184-56 OPENED FALSE DOOR, STAIRLANDING AREA

SECOND FLOOR:

- PA-1184-57 NORTHEAST BEDROOM, LOOKING SOUTH
- PA-1184-58 NORTHWEST BEDROOM, LOOKING SOUTH
- PA-1184-59 NORTHWEST BEDROOM, CLOSETS OPENED
- PA-1184-60 NORTHWEST BEDROOM, LOOKING WEST

DETAIL VIEWS:

- PA-1184-61 MAIN DOORS WITH LOCK RAIL, MAIN HALL
- PA-1184-62 MAIN HALL COLONNADE
- PA-1184-63 MAIN HALL COLONNADE
- PA-1184-64 ENTABLATURE OF MAIN HALL COLONNADE
- PA-1184-65 PEDIMENTED DOORWAY, EAST WALL OF MAIN HALL
- PA-1184-66 BROKEN PEDIMENT OVER DOOR, EAST WALL OF MAIN HALL
- PA-1184-67 BRACKET OF BROKEN PEDIMENT OF DOOR ON EAST WALL OF MAIN HALL
- PA-1184-68 BALUSTRADE AND NEWELL POST, MAIN STAIRWAY
- PA-1184-69 TURNED BALUSTERS AND SCROLLED BRACKETS
- PA-1184-70 PARLOR FIREPLACE ORNAMENTATION
- PA-1184-71 OLD CELLAR FIREPLACE, BLOCKED AND FILLED WITH SHELVES, SOUTH ROOM
- PA-1184-72 JOISTS AND CELLAR FIREPLACE, SOUTH ROOM
- PA-1184-73 paneled closet doors, south wall of northwest bedroom, west of fireplace
- PA-1184-74 closet door of northwest bedroom, south wall, east of fireplace
- PA-1184-75 closet door of northwest bedroom, south wall, west of fireplace
- PA-1184-76 front door lock, east wing

(continued on page 5)

OUTBUILDINGS

- PA-1184-77 GENERAL VIEW OF BARN (STABLE-OFFICE BUILDING), SOUTH ELEVATION.
NOTE CUPOLAS WHICH WERE REMOVED PRIOR TO 1972. Photographed by
Cortlandt V.D. Hubbard, 1967 HABS PA, 51-GERM, 64B-1
- PA-1184-78 BARN (STABLE-OFFICE BUILDING), FROM SOUTHEAST. NOTE ABSENCE OF CUPOLAS
HABS PA, 51-GERM, 64B-2
- PA-1184-79 BARN (STABLE-OFFICE BUILDING), FROM SOUTHWEST HABS PA, 51-GERM, 64B-3

MISCELLANEOUS VIEWS

- PA-1184-80 CLIVEDEN DOORS DAMAGED BY THE BATTLE OF GERMANTOWN, OCTOBER 4, 1777.
Photographed by Cortlandt V.D. Hubbard, 1967
- PA-1184-81 PAIR OF DAMAGED STATUARY IN REAR YARD, TO NORTH OF HOUSE
- PA-1184-82 NOTABLE PERIOD FURNISHINGS, PARLOR
- PA-1184-83 SERPENTINE-FRONT BUREAU, DINING ROOM
- PA-1184-84 OIL PAINTING, BATTLE OF GERMANTOWN
- PA-1184-85 SILOUETTE OF BENJAMIN CHEW
- PA-1184-86 BENJAMIN CHEW'S SIGNATURE
- PA-1184-87 KITCHEN SERVANT SIGNAL BELLS, FIRST FLOOR

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
PA,
51-GERM,
64-

ADDENDUM TO
CLIVEDEN
(THE CHEW MANSION)
6401 Germantown Avenue
Philadelphia
Philadelphia County
Pennsylvania

HABS No. PA-1184

PA-1184-1 through PA-1184-87 were previously transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, March 1982

PA-1184-88 (CT)	SOUTH (FRONT) ELEVATION
PA-1184-89 (CT)	URNS, DORMERS AND CHIMNEYS ON FRONT ROOF
PA-1184-90 (CT)	URNS, DORMER AND CHIMNEY
PA-1184-91 (CT)	STONework OF FRONT ELEVATION
PA-1184-92 (CT)	STONework OF WEST WING
PA-1184-93 (CT)	MAIN HALL, LOOKING TOWARDS REAR PORTION OF HALL, FROM SOUTH
PA-1184-94 (CT)	SOUTHEAST ROOM, NOTE FINE SECRETARY
PA-1184-95 (CT)	SOUTHEAST ROOM, NOTE FINE SECRETARY
PA-1184-96 (CT)	PARLOR
PA-1184-97 (CT)	DINING ROOM, NOTE FIREPLACE AND PANELED WOODWORK
PA-1184-98 (CT)	MAIN HALL COLONNADE
PA-1184-99 (CT)	NOTABLE PERIOD FURNISHINGS, PARLOR

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:

HABS PA-1184

CLIVEDEN

(The Chew Mansion)

6401 Germantown Avenue

Philadelphia

Philadelphia County

Pennsylvania

Photographs HABS PA-1184-1 through HABS PA-1184-99 were previously transmitted to Library of Congress.

INDEX TO COLOR TRANSPARENCIES

Jack E. Boucher, photographer, 1972

PA-1184-100 (CT)	Serpentine-front bureau, dining room. Duplicate color view of HABS PA-1184-83
PA-1184-101 (CT)	View of damaged statuary in rear yard